LC2D●●

W903819410141



LR●D







⚠⚠ DANGER / 危险	
HAZARD OF ELECTRIC SHOCK, EXPLOSION, OR ARC FLASH Disconnect all power before servicing equipment. **Failure to follow these instructions will result in death or serious injury.**	可能有触电、爆炸或者电弧灼伤的危险 在此电力设备上进行操作时，请先断开所有电源。 不遵循上述规定将可能导致人员伤亡。





~	: Alternative current coil
⎓	: Continuous current coil
LC	: Continuous 100mA current coil
AC/DC	: Alternative and continuous current coil

«For Motor Starting Use Schneider Electric Overload Relay Series LR».
“电动机起动请使用施耐德电气LR系列过载继电器”



Schneider Electric Industries SAS
35, rue Joseph Monier - CS 30323
F - 92506 Rueil Malmaison Cedex
www.schneider-electric.com

© 2016 Schneider Electric - All rights reserved.