DATA SHEET

Three Phase Induction Motor - Squirrel Cage



Customer	:							
Product line		: W22 NEMA Premium Efficiency Thre				Product code :	11533060 00718ET3H213TF3-W22	
	Phase	Phase			Catalog # :			
Frame Output Poles Frequency Rated voltage Rated current L. R. Amperes LRC No load current Rated speed Slip Rated torque Locked rotor torque Breakdown torque Insulation class		: 213T : 7.5 HP (5.5 kW) : 4 : 60 Hz : 575 V : 7.34 A : 52.1 A : 7.1x(Code H) : 3.36 A : 1765 rpm : 1.94 % : 22.3 ft.lb : 220 % : 310 % : F : 1.25			Catalog #: Locked rotor time Temperature rise Duty cycle Ambient temperature Altitude Protection degree Cooling method Mounting Rotation¹ Noise level² Starting method Approx. weight³		: 36s (cold) 20s (hot) : 80 K : Cont.(S1) : -20°C to +40°C : 1000 m.a.s.l. : IP55 : IC411 - TEFC : F-3 : Both (CW and CCW) : 58.0 dB(A) : Direct On Line : 159 lb	
Service factor Moment of iner	tia (J)	: 1.34 sq.f	i.lb					
Design		: B	4000	,	F			
Output Efficiency (%)	50% 89.5)	Foundation loads Max. traction		: 311 lb	
Power Factor 0.66		0.76 0.82			Max. compression		: 469 lb	
Losses at norma	ative operating po	oints (spee	ed;torque),	in perce	ntage of ra	ated output power	· · · · · · · · · · · · · · · · · · ·	
P1 (0,9;1,0)	P2 (0,5;1,0)	P3 (0,25;1,0)			4 (0,9;0,5) P5 (0,5;0,5)		P6 (0,5;0,25)	P7 (0,25;0,25
8.8	7.0		6.5	4	1.9	3.3 Non drive en	2.4	1.6
Bearing type Sealing Lubrication inte Lubricant amou Lubricant type Notes:			6308 Z. V'Ring	l	bil Polyrex	6207 ZZ V'Ring - - EM		
This revision replaces and cancel the previous one, which must be eliminated. (1) Looking the motor from the shaft end. (2) Measured at 1m and with tolerance of +3dB(A). (3) Approximate weight subject to changes after manufacturing process. (4) At 100% of full load.				vhich	These are average values based on tests with sinusoidal power supply, subject to the tolerances stipulated in NEMA MG-1.			
(1) Looking the I (2) Measured at (3) Approximate manufacturing p (4) At 100% of fi	motor from the shad with tole weight subject to rocess.	erance of + o changes	after			Performed	Charked	Data
(1) Looking the (2) Measured at (3) Approximate manufacturing p	motor from the shad with tole weight subject to rocess.	erance of + o changes		у		Performed	Checked	Date
(1) Looking the I (2) Measured at (3) Approximate manufacturing p (4) At 100% of fi	motor from the shad with tole weight subject to rocess.	erance of + o changes	after	у		Performed	Checked	Date
(1) Looking the i (2) Measured at (3) Approximate manufacturing p (4) At 100% of fi	motor from the shad with tole weight subject to rocess.	erance of + o changes	after	у		Performed	Checked	Date Revision